

Item 15 Garage inspection



Cotton Tree Garage Assessment

Main Garage Site



Site number	In good repair?	Comments
1A	Yes	
1B	Yes	
1C	Yes	
1	Poor	
2	Yes	
3	Yes	
4	Yes	
5	Poor	Rubbish bin.
6	Yes	
7	Yes	
8	Yes	
9	Yes	
10	Yes	
11	Yes	
12	Yes	
13	Yes	
14	Yes	
15	Yes	
16	Yes	
17	Yes	
18	Yes	
19	No garage as agreed	Site tidy.
20	Yes	
21	Yes	
22	Yes	
23	Yes	
		Electricity sub-station structure in poor condition.
A	Yes	
B	Yes	
C	Yes	Road in poor condition on corner.
D	Yes	
E	Yes	
F		Asbestos between garages F & H.
G	No garage	Historical agreement with PBC before PC took ownership. Site tidy.
H	Fair	Doesn't look like it's being used.

Small Garage Site (near LBS)

Site number	In good repair?	Comments
1	Yes	
2	Yes	
3	Yes	
4	Yes	Parish Council Garage
5	Yes	
6	Yes	
7	Yes	
8	Yes	

Item 15 Garage inspection

Any comments about road surface? ___ The road is in a poor condition on the corner near to garage 'C'. See photos below.



Survey carried out by: CLlr D Barritt

Date: 19th March 2024

Item 15 Garage inspection

