

Report on Countryside Access faults resolved within the Trawden Parish Council area in the 2024/2025 financial year

Reference	Path Number	Location name	Fault description	Action taken
10811	26	Hall Road/ Goose Green Lane	Hidden drain.	We located and cleared the gullies. The first 50m of the pipes were jetted and found to be running clear.
9270	31	Holme Crescent	Lifted flagstones.	With capital funding from Lancashire County Council the flag-stoned steps have been removed and the path re-graded as a ramped path with the flag-stones re-laid and a handrail installed to one side.
11358	35	Cemetery House	New gate required for diversion application route.	Hurdle structure in narrow gateway replaced by the formation a wide gate way and the installation of a Centrewire gate.
10553	84	Hollin Hall	Footpath uneven, slippery and covered in mud.	On investigation we found that the muddy path was not on the strict line of the recorded right of way. We notified the owner and carried out surfacing works without prejudice to any future issue which may require the removal of obstructions on the legal line of the path.
11322	111	Lodge Moss Farm	1. Enquiry about fencing across the footpath. 2. Request for Centrewire gate.	1. We provided advice on the position of the footpath in relation to the proposed fencing. 2. Centrewire gate installed with side fencing and waymark post.
10444	111	Lodge Moss Farm	Field gate across the footpath tied up with bailer twine	We installed a new gate post for the gate to close to with an auto-latch.
10742	115	Lodge Moss Farm	Request for the makeover of a pedestrian gate.	The existing gate was removed and a Centrewire gate installed together with side fencing and waymarking.
10633	141	Near Wanlass Farm	Bottom tread on stile rotten	We replaced the stile with a Centrewire gate with fencing to the side.
10661	142	Near Wanlass Farm	Damaged waymark post.	The old waymark post was removed and a new one installed.
10682	159	Germany Farm	Install 4-way signpost	Signpost installed.

Reference	Path Number	Location name	Fault description	Action taken
10990	171	Bracken Hill	Wobbly waymark post.	Existing waymark post firmed up and re-waymarked with yellow post top.
10632	171	Slackhead Farm	Broken slats on bridge and slippery when wet.	We replaced the existing bridge with a new ditch-crossing and replaced the broken stile with a Centrewire gate.
8092	211	Ferndean Way	Footpath collapse during storm Ciara.	We worked with the adjoining landowner to create a temporary footpath. The original footpath was subsequently rebuilt after the collapsed section of land was reinstated with rock filled bags. The work included the reinstatement of the land for the temporary footpath and repairs to the boundary drystone wall.