

Grot Spot Form – May 2025 Ball Grove Park

Location	Issue	Action
Near playground/bottom of footpath	Fallen edging stones	Ask Leo Brightley to repair
Between top car park and side of lake	Steps from car park are a hazard.	Once grip strip installed, remove?
Corner of car park next to lake	Stone been moved	Install bigger stone
Wall on river side needs attention	Various issue sin various places. Adrian to compile report on works required.	
Winewall Road Car Park	Extra boulder required to block possible entrance point onto park area near LBS	
Wall along river assed for condition	Height issues.	
Height Barrier at Winewall Road car park	Pins need removing from barrier and supporting structure.	Repairable with the right equipment.