

Item 20 Grot Spots

Grot Spot Walk 23/10/21

Location	Issue	Responsibility	Reported?
Tram Tracks	2 nd & 3 rd garage from bottom on right hand side need attention	Tenant – AW to contact person responsible for collecting rent.	
Top of Tram Tracks	Dog poo bin off its post	PBC	Yes - SCP
Bus Terminus	Post next to phone box needs painting	TFPC – AW to report to AC	Yes
Bus Terminus	Phone box – could this be a location for a defibrillator	AW to send request to SCP	Yes
Garage Site at Boulsworth Drive	2 garages need attention. General tidy up and replace signage	Together Housing Together Housing	Yes - SCP
Lane House, Ash Street, Church View	Rusty Signs Sign falling off backing wood	PBC PBC	Yes – SCP Yes - SCP
48-54 Church Street	Front gardens need tidying		
Library/Shop	Tree looks dead Re-stake trees to correct positioning	Community Centre Trustees Community Centre Trustees	
Church Street	Post box needs repainting	Post Office	Yes - SCP
Junction of Forest Bank with Skipton Road	Requires Lining	LCC	Yes - SCP
Railings at bottom of Dean Street	Bent	LCC	Yes - SCP
Outside Lyndene and Avondale, Lane House	Tarmac where flags should be	LCC	Yes - SCP
Near to Nichol House Farm	Footpath sign covered by foliage	PBC	Yes - SCP

Item 20 Grot Spots

Land near to Nichol House Farm	Fly tipping, parking of trailers on designated footpath	PBC	Yes - SCP
Tram Tracks	Gate to plot off Tram Tracks to storage area needs attention	Tenant – AW to contact person responsible for collecting rent.	
Brooke Mill House	Excessive amounts of debris on and around the property	PBC	Yes - SCP
Grid at Brooke Mill House	Grid Blocked	LCC	Yes
Bus Shelter at Dean Street	Smashed glass panel	TFPC	